
Smoke and Dye Testing Summary

High Level Sewershed

Run Summa	Run Summary ————————————————————————————————————						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-068	Smoke	9/8/2008	ADS/TM	S13CC1032MH	Dry	Yes	467.27



Smoke and Dye Testing Summary

High Level Sewershed

Run Summa	Run Summary ————————————————————————————————————						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-068	Smoke	9/8/2008	ADS/TM	S13CC1032MH	Dry	Yes	467.27

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13CC1032G1	S13CC1032MH	S13CC1002MH	238.8748	8
S13CC1029G1	S13CC1029MH	S13CC1032MH	228.3994	8

Observations & Photos

Obs_ID S1028-068-OB01 **Address** 3928 Reisterstown Rd

StatusPrivateSourceCleanoutLocationYard - front

Nearest MH S13CC1032MH

Comments Smoke from cleanout in front yard. 3928

Reisterstown Rd



Picture \S1028-068-OB01-P01.jpg

Comments Front of house, 3928

Reisterstown Rd

Obs_ID S1028-068-OB02 **Address** 3926 Reisterstown Rd

Status Private **Source** Cleanout

Location Yard - front **Nearest MH** S13CC1032MH

Comments Smoke from cleanout in front yard. 3926

Reisterstown Rd



Picture \S1028-068-OB02-P01.jpg

Comments Front of house, 3926

Reisterstown Rd